SUMMARY OF DAMAGE CASES FROM THE DISPOSAL OF MINING WASTES

VOLUME II

APPENDICES E-L

Contract No. 68-02-3179

Prepared For:

U.S. ENVIRONMENTAL PROTECTION AGENCY
Office of Solid Waste
401 "M" Street, SW
Washington, D.C. 20460

Prepared By:

SCS ENGINEERS 11260 Roger Bacon Drive Reston, Virginia 22090 (703) 471-6150

March 5, 1984

Reproduced and Distributed by the



American Mining Congress
Suite 300 1920 N Street NW Washington DC 20036

40504935 Superfund

04-00

3/5/84

Unknown

call with Inactive lead, zinc, copper mine/ mill

OWNER:

NL Industries

LOCATION:

Northeastern Madison County, MO

**NEAREST WATER BODY:** 

Toler Creek to Saline Creek to

Little St. Francis River

WASTE TYPE INFORMATION:

Tailings (crushed rock, clay and fines)

MANAGEMENT METHOD:

Tailings pond

PROBLEM:

Major dam failure 3/28/78 releasing massive amounts of tailings from 40 acre pond into the drainage flow of Toler Creek.

NATURE AND EXTENT OF DAMAGE:

Several hundred acres of agricultural land covered by as much as 1 ft thick layer of tailings. Deposited sediment drastically reduced or eliminated crop production value of land. Primary water quality damage due to physical effects of sediment since heavy metal concentrations in stream samples did not exceed limits of tolerance by bentric fauna. Turbidity increase was noticable 5 miles downstream from Saline Creek confluence with the Little St. Francis River.

PARAMETERS:

Density and diversity of benthic organisms were studied and turbidity levels established. Dissolved metal concentrations are summarized in appended Figures (copies of Figures 5 and 9 from Missouri Department of Conservation Report in 1980).

REVERSIBILITY/MITIGATIVE EFFORTS:

Dam repaired. If any sediment removed, it was not documented in the available references.

COSTS: N/A

REFERENCE: MO-M-NL




Figure 1. Sampling stations on Saline Creek and the Little St. Francis River, Madison County, Missouri, 1977-78.

